



CONGRESS HEIGHTS REC LEAD WATER TEST RESULTS May 16th, 2016



	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	CONGRESS HEIGHTS REC CTR	5/24/2016	WS- 005378	Utility	1	In storage room (water source)	WT-042916-5395- A	2.2	WT-042916-5395- B	< 1				
2	CONGRESS HEIGHTS REC CTR	5/24/2016	WS- 005379	Cooler	1	In hall / classroom	WT-042916-5396- A	< 1	WT-042916-5396- B	< 1				
3	CONGRESS HEIGHTS REC CTR	5/24/2016	WS- 005380	Fountain	1	Exterior adjacent to playground Left Low	WT-042916-5397- A	< 1	WT-042916-5397- B	< 1				
4	CONGRESS HEIGHTS REC CTR	5/25/2016	WS- 005381	Fountain	1	Exterior adjacent to playground Right High	WT-042916-5398- A	< 1	WT-042916-5398- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.